

SMYTHESDALE GARDENS & BREWERY DAM RESERVE MASTERPLAN 2023

ACKNOWLEDGEMENT OF COUNTRY

Golden Plains Shire spans the Traditional lands of the Wadawurrung and Eastern Maar people. We Acknowledge them as the Traditional Owners and Custodians.

Council pays its respects to Wadawurrung Elders past, present and emerging. Council also respects Eastern Maar Elders past, present and emerging.

Council extends that respect to all Aboriginal and Torres Strait Islander People who are part of the Golden Plains Shire.

Contents

- 1. Introduction and background
- 2. Location
- 3. Strategic Alignment
- 4. Consultation & Engagement
- 5. Site SWOT Analysis
- 6. Master Plans Garden Reserve Brewery Dam
- 7. Implementation Framework

Appendix A: Hazard identification Risk Assesment Brewery Dam Appendix B: Symthesdale Gardens Arborist report 12 Feb 2014 Appendix C: Symthesdale Gardens Arborist report 11 May 2023







fitzgerald frisby landscape architecture

Smythesdale Gardens & Brewery Dam Reserve Master Plan

- 1
- 2
- 7
- 11
- 13
- 15
- 15
- 16
- 17



Introduction & Background 1.

Golden Plains Shire Council commissioned the development of new master plans to guide the future planning and development of the Smythesdale Gardens & Brewery Dam Reserves. Key objectives of the master planning process were to:


- Improve and enhance the reserve landscape. ٠
- Improve and enhance recreation opportunities for a range of reserve users. ٠
- ٠
- ٠
- Ensure each reserve is accessible and appealing to all members of the community.
- ٠ Resolve existing circulation and access issues.
- ٠ and within resource constraints.

The overarching aim of the master plan is to provide a realistic and achievable vision for both reserves to guide future decision-making, resource allocation and improvement opportunities at each site.



Undertake consultation with user groups and residents to establish current and future needs and issues. Document options for additional facilities or infrastructure that could help address community needs.

Develop a master plan that provides clear direction for the development of each reserve that is realistic



Location 2.

Smythesdale Gardens Reserve

Smythesdale Gardens is located at 33 Garden Street, Smythesdale. It is bounded by Garden Street to the south, Willis Street to the north and west, and the Ballarat-Skipton Rail Trail to the southeast. The 3.0 hectare site comprises multiple individual allotments of Crown land. It is zoned 'Rural Living' under the Golden Plains Planning Scheme, and is subject to the Bushfire Management, Design & Development, and Significant Landscape overlays.

The site is Department of Energy, Environment and Climate Action (DEECA) owned Crown Land, delegated to Council and managed by a Committee of Management on behalf of Council (i.e. Smythesdale Progress Association). The Community Committee manages the site as an unpowered camping destination ("free camp") and invites donations from users to help fund asset maintenance and improvements (annual revenue reportedly around \$12k p.a.).


The site has a mix of established native trees and cleared open space. It is an attractive area with a high amenity landscape and is much valued by the local community. Historically the site was established as a modest botanic garden with suggestions the renowned botanist Ferdinand Jacob Heinrich von Mueller was involved in early planning for the reserve in the late 1850's. Regardless of origins, the site retains a mix of native and exotic European trees, many of which are reaching senescence and require strategic removal and replacement.

The site is one of two approved camping sites in the Shire with associated facilities including camp hut, fire pits and shelters, a shower block, public toilets, and local play space. It is also well used by the local community for a range of active and passive recreation activities including community gatherings, family outings, picnicking and informal play.

Smythesdale Brewery Dam Reserve

The Smythesdale Brewery Dam Reserve is situated at 29 Sebastopol-Smythesdale Road, Smythesdale. The site comprises multiple individual allotments of Crown land, delegated to Council and managed by a Committee of Management on behalf of Council.

The Brewery Dam site is a designated community open space area which consists of a mix of established native trees, cleared open space and a large dam with a fishing pier. The site is largely hidden within a bush setting, however provides opportunities for passive recreation including picnicking, nature appreciation, vabbying and fishing. Swimming is not permitted. Council and the community are keen to explore opportunities to increase the use and amenity value of the reserve.




Ecological Vegetation Class

Prior to any infrastructure works Councils Environmental and Sustainability team must be notified to help avoid and minimise impacts on native vegetation through sensitive and sensible design. If infrastructure works are to impact areas of native vegetation then a detailed native vegetation assessment by a consultant may be required.

The Smythesdale Gardens Reserve contains introduced tree species and has mapped Ecological Vegetation Class (EVC) 47 Valley Grassy Forest (Vulnerable) within the site. Characterised as an open forest to 25m tall it may carry a variety of eucalypts, usually species that prefer more moist or more fertile conditions over a sparse shrub cover with a rich array of herbs, lilies, grasses and sedges dominate the ground layer. Much of this has been extensively cleared and smaller remnants are now mainly confined to the area adjacent to the Ballarat Skipton Rail Trail.


Brewery Dam Reserve contains both native and non-native species. It has mapped EVC Heathy Dry Forest (EVC20) which is charaterised as an open eucalypt forest to 20m tall with an understorey dominated by a low, sparse to dense layer of shrubs including heaths and peas and grass ground layer. Brewery Dam has been extensively modified over time and the native vegetation is slowly recovering. The former CFA training site has had much of its overstory removed and is now dominated by native grassland species Kangaroo Grass (Themeda triandra), this is a unique and important attribute to Brewery Dam Reserve.



Land Use Planning Zones and Planning Overlays

Land use planning zones and planning overlays help identify designated land uses, environmental significance, areas of cultural sensitivities and land subject to inundation. Both Smythesdale Gardens and Brewery Dam Reserve are in a designated bushfire prone area. The first set of maps are showing Smythesdale Gardens. following by Brewery Dam Reserve.

Smythesdale Gardens



Smythesdale Gardens & Brewery Dam Reserve Master Plan


Smythesdale Gardens is located within the Rural Living Zone and continues into the northern and western boundaries. To the east, there are Commercial 2 Zones and the Symthesdale Township to the South.

Landscape overlays seek to protect vegetation or landscape features of an area and are used to recognise areas of landscape significance. The SLO through Smythedale Gardens is to ensure that the significant heritage trees found throughout the site are protected.

The south-western area of this property is an 'area of cultural heritage sensitivity'. 'Areas of cultural heritage sensitivity' are defined under the Aboriginal Heritage Regulations 2018, and include registered Aboriginal cultural heritage places and land form types that are generally regarded as more likely to contain Aboriginal cultural heritage.



Brewery Dam Reserve




Smythesdale Gardens & Brewery Dam Reserve Master Plan

Brewery Dam Reserve is located within the Public Conservation and Recource Zone. Rural living Zone is located to the north and east of the reserve, while the Commercial 2 Zone is located to the west. The Smythesdale Township is located to the south-west of the reserve.

--- Study area

A small area within the Brewery Dam Reserve is Land Subject to Inundation. It does not have any conflict with Vegetation Protection, Environmental Significance, or Significant Landscape overlays.





Smythesdale Gardens Camping Income and Patronage

The revenue generated from camping donations can be seen in the rise in annual camping income. There was a steady increase of income from 2013 - 2019. Income then declined due to COVID 19 Patronage and income has increased following cessation of COVID restrictions with total camping income in 2021/22 rising.

In general, usage increases during the warmer months and during major holidays particularly Christmas and Easter.



Smythesdale Gardens & Brewery Dam Reserve Master Plan

3. Strategic Alignment

It is important that the master plans align with key strategic directions of Council and the community. A snapshot of key influences informing the master plan are outlined below.

Council Plan (incorporating Municipal Public Health and Wellbeing Plan) 2021-2025

The Council Plan details the priority initiatives and actions for Council services, infrastructure, and advocacy to be provided to the Golden Plains Shire community through to 2025.

The Plan supports the themes of the Golden Plains Community Vision 2040: Community; Liveability; Sustainability, Prosperity (and Leadership).

The Council Plan details Strategic Objectives and key actions for delivery during the Council term. Whilst development of the master plans is not specifically referenced, the project aligns with key themes aimed at improving community infrastructure provision, protection of natural, cultural and heritage environments as well as the provision of attractive, functional open spaces that support community health, wellbeing, and recreation. Priority outcomes incorporated into the Public Health and Wellbeing Plan that can be supported in the master plans include:

- Improved access to safe built environments using universal design principles, including community ٠ facilities and spaces, open space, and places for active recreation.
- Preserved natural environment and ensuring the community is resilient and responsive to the challenges of climate change and emergency management.
- Healthy and sustainable environments.
- Connected communities.

Sport and Active Recreation Strategy 2020-2030


The Strategy identifies strategic priorities for sport and active recreation provision and improvement opportunities to address community needs over a ten-year timeframe.

In relation to Smythesdale, the Strategy recognises that most regional level facilities are provided in neighbouring Ballarat but identifies a significant opportunity to further enhance equestrian facilities in the Shire. It suggests such facilities could attract State and National level events. Smythesdale Gardens could be used to support equestrian events by providing low-cost accommodation / camping options, as well as through equestrian use of the adjacent rail trail.

Available activities listed in the Strategy in Smythesdale include Basketball, BMX, Cricket, Cycling (off road trail), Fitness classes, Football, Horse Riding, Netball, Play, Running, Skateboarding, Tennis, Walking and Petangue. The Strategy does not provide specific direction for Smythesdale Gardens or Brewery Dam reserves, other than continuing to support the informal recreation needs of the local community.







Smythesdale Community Plan 2021-2024

Community Planning is a process that brings people together to consider issues and take action to improve their community. Community members develop a plan that outlines projects they will undertake to make their town a better place to live. Key initiatives relevant to the master plans include:

- Further strengthen opportunities for our community to come together, increase local participation and a sense of community pride.
- Beautification and art initiatives including additional art sculptures at the Smythesdale Gardens
- and flood mitigation.
- Community working bees that have a focus on the environment.

dy area considers the towns of Scars 10 INTRODUCTION vn as part of an integrate the commercial and commercial and commercial and commercial and commercial and commercial scarsd

ale to he 312



(since 2013) nrc

standing the sig

1 Purnose

1.2 Covid Contex

1.3 Study Area

Sustainable 1.5 Demographic



Smythesdale Structure Plan (Background Report), 2021

The Structure Plan considers future land uses to support the continued growth of Smythesdale whilst maintaining the appeal and unique features of the town.

Smythesdale is one of two towns in Golden Plains Shire that is sewered (since 2013), providing the opportunity for some medium density allotments within the sewer district. Smythesdale is strategically positioned with good access to Ballarat.

Council and the community considered a population of 2,500 as a suitable size for Smythesdale to improve the sustainability of retailing and other business activities in the township. The 2016 census population for the Smythesdale locality was 1,037 people. A further 744 persons were counted for the Scarsdale district and the Newtown locality recorded a population of 118 persons. The combined total is 1,899 people.

The current population falls short of the 2,000-2,500 identified as realistic and sustainable for Smythesdale in the 2006 Smythesdale Urban Design Framework.

Based on 2016 census data and growth rates, the projected population of Smythesdale and Scarsdale will be near to 3,000 people by 2041. To reach a population of 3000 persons, an additional 440 lots is required. This will service the township for the next 25 years until 2046 at a growth rate of 4%.

Smythesdale is surrounded with an abundance of natural and passive open spaces including the Smythesdale/ Ngarinyook State Forest. Woady Yaloak River, Smythesdale Streamside Reserve; Smythesdale Recreation Reserve, Smythesdale Gardens; Brewery Dam; Argyle Dam, Surface Hill Historic Reserve; Watson's Hill Bushland Reserve. All of these provide Smythesdale with ready access to the natural environment and offer unique experiences from horse riding; picnicking; bushwalking, cycling and other outdoor experiences.

The master plans will therefore support continued community access to the Gardens and Brewery Dam sites, the former with an emphasis on supporting tourism and economic development through camping and the later for informal recreation.

Advocating for environmental management and improvements as well as supporting fire management



CONCEPT MASTERPLAN

PROPOSED ACTION PLAN
1. Remove Monterey Cypress trees (Trees 15-19, 20, 21, 24 & 26) along north & west side of events space, and replant with fast-proving shade trees (eg Wattes) for quick shade, and long-lived evergreens (eg confirer). Mass-plant small areas around prior: area nodes to provide shefter and privacy. Construct perimeter path and gravel picnic area nodes (see 5 below).

- Undertake urgent actions identified in Arborists report, including tree removal and deadwooding, relocating seats from under high-risk trees.
- Create a linking pathway between the camping area and toilets/BBQ area.
- 4. Creating a direct pathway link to the Rail Trail.
- Create a gravel perimeter pathway linking picnic areas and gravel picnic areas 'nodes' of varying sizes for large and small groups, with tables and benches.
- Construct two additional picnic shelters for tent campers and other garden users.
- 7. Upgrade grassed area for events as demand requires.
- Develop attractive shaded lawn area adjacent to SS Monterey as an alternative picnic space.

- 9. Install gates and bollards to manage vehicle access to event space. 10. Provide fire pits for campers and other garden users.
- 11. Screen planting between the camping area and event space. Locate the memorial seats along the perimeter path and install interpretive signage regarding the history of the gardens, and the significance of the local identities who are honoured on the seats.
- 13. Relocate and screen rubbish bins.
- Remove the fence around the playground to open up visual connection to the carpark. Pland shrubs and trees around the carpark as a windbreak.
- Creatively respond to tree removals, creating themed sculptures as the opportunity arises.
- 16. Undertake drainage improvements of low-lying areas.
- 17. Create rest area at rail trail entry with signage, water tap and seat.
- Prepare landscape plan for staged replanting of senescent and high-risk trees, starting with replanting trees on the north side of the events space as noted above (Action #1).
- Potential location of ornamental garden beds, design and extent to be determined (potentially part of the landscape plan brief noted above). Arrangement shown is indicative only.





CONCEPT MASTERPLAN Smythesdale Gardens Reserve (former Smythesdale Botanic Gardens) ANDSCAPE ARCHITECTURE Revision: B È Date: 17/02/10

Irrigated Lawr

Kikuyu grass

Proposed Path Concrete pavers or o

Picnic Area Node

Smythesdale Gardens Concept Master Plan (2016 & 2019)

The Committee of Management previously commissioned the development of a Concept Master plan for the Smythesdale Gardens site in 2016. The plan was not formally adopted by Council, however provided operational management and landscape improvement guidance to the Committee, including selected tree replacement.

The table below extracts the key actions outlined in the 2016 Plan and provides a comment on current implementation status (based on visual inspection) and ongoing relevance to this new master plan for the site.

2016 Action Plan	Implementation Status	Ongoing Relevance
1. Remove Monterey Cypress trees (Trees 15- 19, 20, 21, 24 & 26) along north & west side of events space, and replant with fast-growing shade trees (eg Wattles) for quick shade, and long-lived evergreens (eg conifers). Mass-plant small areas around picnic area nodes to provide shelter and privacy. Construct perimeter path and gravel picnic area nodes (see 5 below).	 Partially completed i.e. some selected tree removal, limited replanting and gravel path not established. 	 Review path network, layout and connections Subject to new Arborist report, remove high-ris senescent trees where required.
2. Undertake urgent actions identified in Arborists report, including tree removal and deadwooding, relocating seats from under high-risk trees.	 Partially completed unable to confirm Arborist Report. 	 Subject to new Arboris report, remove high-ris senescent trees where required. Review and recommend seating locations.
3. Create a linking pathway between the camping area and toilets/BBQ area.	Not Completed	Review path network, layout and connections
4. Creating a direct pathway link to the Rail Trail.	Completed.	Review path network, layout and connections
5. Create a gravel perimeter pathway linking picnic areas and gravel picnic areas 'nodes' of varying sizes for large and small groups, with tables and benches.	Not completed.	 Review path network, layout and connections
6. Construct two additional picnic shelters for tent campers and other garden users.	Partially completed – 1 shelter completed.	Review locations for picnic shelters.
7. Upgrade grassed area for events as demand requires.	Completed	Consider opportunities to further enhance the 'events' space.
8. Develop attractive shaded lawn area adjacent to SS Monterey as an alternative picnic space.	Completed	Retain.



Landscape Site Plan

Symthesdale Garden - Map of Designated Camping Areas 2/2019 | Revision: B erence: 30042638.00 | Drawing: 01 Checked by: N Lamb 0 5 10 15 20 25m Scale 1500 @ A1



2016 Action Plan	Implementation Status	Ongoing Relevance
9. Install gates and bollards to manage vehicle access to event space.	Completed	Review traffic controls throughout.
10. Provide fire pits for campers and other garden users.	Partially completed.	Review possible locations for fire pits (remove undesirable locations).
11. Screen planting between the camping area and event space.	Not completed.	Review screen planting.
12. Locate the memorial seats along the perimeter path and install interpretive signage regarding the history of the gardens, and the significance of the local identities who are honoured on the seats.	Partially completed – not all seats have been relocated from under trees.	 Review seating locations.
13. Relocate and screen rubbish bins.	Partially completed – limited screening.	Review rubbish bin 'enclosure'.
14. Remove the fence around the playground to open up visual connection to the carpark. Plant shrubs and trees around the carpark as a windbreak.	Partially completed	 Review playground location.
15. Creatively respond to tree removals, creating themed sculptures as the opportunity arises.	Partially completed.	 Support ongoing installation of art and sculptures utilising tree stumps.
16. Undertake drainage improvements of low-lying areas	Partially completed.	 More significant drainage infrastructure / management required to address ongoing issues.
17. Create rest area at rail trail entry with signage, water tap and seat	Partially completed -signage and access to water provided.	Review seating locations.
18. Prepare landscape plan for staged replanting of senescent and high risk trees, starting with replanting trees on the north side of the events space as noted above (Action #1).	Not completed.	 Subject to new Arborist report, remove high ris senescent trees where required.
19. Potential location of ornamental garden beds, design and extent to be determined (potentially part of the landscape plan brief noted above). Arrangement shown is indicative only.	Not completed.	Review locations for additional planting and landscape improvements.

Subsequent to the 2016 Master Plan, a 'site plan' was also documented in 2019 which illustrated designated camping areas and existing infrastructure; however, it did not provide specific actions or recommendations for future improvement.



4. Consultation & Engagement

Initial Engagement

As part of the initial situation analysis, the consultant team met on-site with representatives of the Progress Association/Committee of Management and facilitated a workshop with a selection of Golden Plains Shire staff. Key comments, issues, or suggestions for improvement at each site are summarised below.

Smythesdale Gardens

Committee of Management

- Construction of brick gutters in main parking area (help address drainage and wash-outs).
- Improve road drainage at 3rd entrance off Gardens St.
- Installation of concrete slabs under garden benches.
- Repainting of garden benches.
- Renovate/replace showers and amenities.
- Improve/address drainage throughout site.
- Additional art installations proposed for the tree at the entrance to complement existing Eagle.
- Gravel roads wash out.
- Consider installation of permanent fireplaces in selected locations.
- Maintenance issues vegetation in drainage lines, wheelie bins need more regular collection (by Council, currently weekly - particularly after weekend camping).
- Adjacent 4WD club/land no negative impact on site. No interest in accruing more land for camping
- Consider traffic speed control speed humps
- Keep/support European vegetation.
- Replace senescent Pines.
- Horses use the Rail Trail consider holding yards/trailer parking to support. Existing water trough adjacent to trail.
- Review / install signage at the front entry to the reserve.
- Need a path connection to link to the Creek Trail.
- Consider installation of fitness equipment/features.
- Currently 17 'memorial' park seats throughout the site require maintenance, concrete pads and define locations - considering safety from trees.
- Committee operates on approx. \$12kp.a. revenue from 'donations/camping fees'.

Council Staff

- Flood and drainage across site to be resolved.
- Better define camping areas, parking and vehicle circulation.
- Amenities outdated, require refurbishment or replacement (possibly include new modern 'camp kitchen')
- Park furniture review/replace.
- A new sub-regional play space to be developed at the Recreation Reserve, therefore 'local' play only at the Gardens site.
- Improve the reserve to support broader economic development in the town (i.e. 'stay and play').
- Highly used for free camping.
- The site was raised as a possible option to establish 'permanent' accommodation for Windfarm Workers - then transition to camping accommodation. However, this increases management complexity and therefore not supported.
- Tree management and replacement needed. Continue European species (i.e. Former 'botanic garden').
- Significant landscape overlay.
- Bushfire overlay access, water access considerations.
- Introduce tree protection zones camping safety.
- Review pedestrian path connections and standards (1.8m wide shared).
- Approx. middle of the Rail Trail route ideal overnight stop.



Brewery Dam

Committee of Management

- · Construction of pathway around the dam. Likely to require a raised walkway/bridge across eastern side of dam.
- Improve entrance track and parking area grading, additional gravel/road mix. Improve road drainage at entrance.
- Consider recycled plastic park furniture not wood. Wood often vandalised, burnt or stolen. Improve drainage to create better overflow drainage and flow into the dam, to maintain a consistent depth
- Primarily a fishing/picnic site.
- Retain or replace existing fishing jetty.
- Former Fire Training Track at the front of the property no longer used/required.

Council Staff

- Enhance informal recreation opportunities. Potential native garden attraction. •
- Dam may be spring fed rarely/never empty.
- Risk assessment may be required prior to encouraging additional community use. (NB: a risk assessment was subsequently undertaken by Council staff - refer Appendix). 'Uncontrolled' overflowing of the dam an issue - potentially compromising the dam wall integrity. Consider
- options to resolve.
- Upgrade the gravel car park area better definition and maintenance (remove 'internal' road).

Public Exhibition

Following consideration of the Smythesdale Gardens and Brewery Dam Reserve Draft Master Plan at its meeting on Tuesday, July 25, 2023, Golden Plains Shire Council sought additional community input via public exhibition of the draft material between Wednesday 26 July to Wednesday 23 August 2023.

The Draft Master Plan was heavily promoted by Council's Communications & Engagement team during the public exhibition period, however, only two formal submissions/survey responses were received. In addition, a further email was received from the Smythesdale Progress Association/Gardens Committee of Management.

All feedback indicated in-principle support for the directions outlined in the Draft Master Plan, however suggestions for improvement and/or clarification were requested in relation to potential for more permanent accommodation at Smythesdale Gardens, treatment of the central overland flood area (at the Gardens) as well as landscape treatments, traffic management, flood flow and rubbish removal at the Brewery Dam site.

All feedback has been considered in the subsequent updating of the Master Plan (i.e. this report), however it is acknowledge that some feedback would need to be considered in future detailed designs for on-ground works at each respective site. There was no feedback, comments or suggestions that warranted any major changes to the initial draft master plans.



5. Site SWOT Analysis

Having regard to the situation analysis, site assessment and initial stakeholder engagement, the following summary Strength, Weaknesses, Opportunities and Threat (SWOT) analysis has been undertaken to inform the master plans for each site.

Gardens Reserve:

Str	engths:	We
•	Former Botanic Gardens – mix of vegetation and exotic trees. Popular 'free camping' area. Community event space. Adjacent to existing Ballarat-Skipton Rail Trail (half-way point). Relatively close to central business district and town attractions, including recreation reserve. Proactive community-led management. Existing sewage dump-point. Adjacent to Ballarat and District 4WD Club land. Art installations. Overall size – generous areas for informal	• • • • • • •
•	camping. Playground / Pirate ship. Camp shelters. Internal perimeter (gravel) road provides good access to all sites. Arborist Assessment recently completed for all trees.	
On	portunities:	
Ob	portunities.	Th
•	Improve condition of the event space lawn (e.g. irrigation / watering / grass cover). Improve pedestrian circulation and path network. Improve site drainage – utilising a combination of engineered infrastructure and natural areas (e.g.	•
•	Improve condition of the event space lawn (e.g. irrigation / watering / grass cover). Improve pedestrian circulation and path network. Improve site drainage – utilising a combination of engineered infrastructure and natural areas (e.g. overland flow). Better define camping areas/sites.	•
•	Improve condition of the event space lawn (e.g. irrigation / watering / grass cover). Improve pedestrian circulation and path network. Improve site drainage – utilising a combination of engineered infrastructure and natural areas (e.g. overland flow). Better define camping areas/sites. Review traffic circulation and internal roads –	•
•	Improve condition of the event space lawn (e.g. irrigation / watering / grass cover). Improve pedestrian circulation and path network. Improve site drainage – utilising a combination of engineered infrastructure and natural areas (e.g. overland flow). Better define camping areas/sites. Review traffic circulation and internal roads – including access to camping sites. Enhance landscaping, including garden beds to separate/define areas.	•
•	Improve condition of the event space lawn (e.g. irrigation / watering / grass cover). Improve pedestrian circulation and path network. Improve site drainage – utilising a combination of engineered infrastructure and natural areas (e.g. overland flow). Better define camping areas/sites. Review traffic circulation and internal roads – including access to camping sites. Enhance landscaping, including garden beds to separate/define areas. Improve campfire facilities	•
•	Improve condition of the event space lawn (e.g. irrigation / watering / grass cover). Improve pedestrian circulation and path network. Improve site drainage – utilising a combination of engineered infrastructure and natural areas (e.g. overland flow). Better define camping areas/sites. Review traffic circulation and internal roads – including access to camping sites. Enhance landscaping, including garden beds to separate/define areas. Improve campfire facilities Holding yards for horses using the Rail Trail – overnight camping. Path connection to link to Woady Yaloak Creek / River Trail.	•
•	Improve condition of the event space lawn (e.g. irrigation / watering / grass cover). Improve pedestrian circulation and path network. Improve site drainage – utilising a combination of engineered infrastructure and natural areas (e.g. overland flow). Better define camping areas/sites. Review traffic circulation and internal roads – including access to camping sites. Enhance landscaping, including garden beds to separate/define areas. Improve campfire facilities Holding yards for horses using the Rail Trail – overnight camping. Path connection to link to Woady Yaloak Creek / River Trail. Improve site signage – interpretive and regulatory.	•
•	Improve condition of the event space lawn (e.g. irrigation / watering / grass cover). Improve pedestrian circulation and path network. Improve site drainage – utilising a combination of engineered infrastructure and natural areas (e.g. overland flow). Better define camping areas/sites. Review traffic circulation and internal roads – including access to camping sites. Enhance landscaping, including garden beds to separate/define areas. Improve campfire facilities Holding yards for horses using the Rail Trail – overnight camping. Path connection to link to Woady Yaloak Creek / River Trail.	• •

٠ Improved management of existing trees and implementation of a tree replacement strategy. Weaknesses:

- Aged amenities block showers and toilets.
- Poor drainage throughout site.
- Gravel roads and path washouts.
- Poorly defined pedestrian routes / paths.
- Ageing infrastructure, including park furniture,
- fencing and bollards.
- Memorial seating age, condition, and locations. Gravel access roads at entry – including swale crossing (drop-off).
- Lack of entry signage.
- Lack vehicle speed controls.
- Unattractive wheelie-bins at front entrance.

reats:

- Senescent trees potential risks form falling tree/ limbs. Introduce tree protection zones - camping safety.
- Fire bushfire and camping fires.
- Flooding impacting on access and use of the reserve.



Brewery Dam:

Brooke Street.

Sti	rengths:	W
•	Attractive 'natural' area. Permanent water – 'spiring fed' dam. Native vegetation and bushland character.	•
•	Complements other open space offerings in Smythesdale.	•
	Sinythesuale.	•
		•
		•
		•
		•
Op	oportunities:	Tł
•	Support informal community use e.g. yabbying, walking, picnicking etc. Improve site signage – including risk mitigation, regulations, and warnings, including No Swimming. Establish circuit path, including boardwalk where required. Replace existing pier/jetty with best-practice design	• • • •
•	(as per Risk Assessment, Appendix 1). Upgrade car park, access road and entry signage. Remove former CFA Training Track and	Ū
	infrastructure from front of the property. (It is acknowledged the CFA infrastructure is technically outside the study area).	
•	Establish and new entry feature to help identify the site.	
•	Install / replace park furniture at key locations. Reinforce indigenous / native planting and vegetation – including to improve access barriers to the dam edge.	
•	Better control access to the waters edge to defined locations.	
	Establish a new pedestrian connection to / from	

leaknesses:

- Low levels of use.
- Relatively isolated site, not well known or accessible – i.e. lack signage or entry features. Poorly resolved water flow control, including overflow.
- 'Uncontrolled' overflowing of the dam potentially compromising the dam wall integrity. Explore options to resolve.
- Proximity of private property interfaces.
- Lack of perimeter / loop path.
- Poorly defined access and accessability of entry path.
- Lack defined paths.
- Age, condition, design and location of existing jetty/pier – jetty was fully submerged during one site visit.
- Poor condition and amenity provided by existing car park and furniture – including limited vehicle controls.

hreats:

- Drowning water interface.
- Water hazards and risks.
- Vandalism including park furniture and signage. Bushfire / informal fires.
- Antisocial behaviour relative isolation of the site. Periodic risk assessment required.
- Current lack of regular maintenance and the ability to maintain additional facilities

6. Master Plan

Smythesdale Gardens



Recommendations:

- Reference on Master Plan refers to all trees.
- to minimise the loss of camping spaces.
- consistency across the site.
- S5
- S6
- S7 facility.
- S8 shelter.
- into potential amenity block upgrade.
- communal campfire locations.
- required.
- Creek.
- reduce compaction under existing trees.
- or tiny house style accommodation.

Implement recommendations from arborist assessment and develop a Tree Replacement Strategy to retain the current landscape character as senescent trees need to be replaced. Refer to Appendix C for arborist assessment.

Restrict access and revegetate overland drainage area to create a park feature and prevent vehicles being bogged. Detailed design to be completed

Undertake a drainage assessment of all roads including the entry area to identify scope of works required for upgrade. Explore options to transfer management / maintenance responsibilities for internal roads to Council and include on Council's annual unsealed road maintenance program.

Upgrade existing entrance signage and update existing internal signage. To be in accordance with Council open space reserves identification signage and

Add additional historic signage within the gardens to share the rich site history

Upgrade existing crossover at main entrance to create a safer access for vehicles with caravans i.e. prevent wheel drop-off drainage crossing

Consider options to upgrade or replace the existing toilet and amenities

Consider options to upgrade or replace the existing camp kitchen/BBQ

Investigate the level of use and ongoing demand for the existing "administration" building. If long-term use is required, upgrade/refurbish the existing building or consider building consolidation and incorporate function/s

Subject to review of Council Local Laws (i.e. fire restrictions), construct three

Upgrade the event lawn grass surface with irrigation and drainage where

Upgrade path network and connections to the Rail Trail and Woady Yaloak


Undertake a traffic circulation review to include internal roads and access to camping sites. Refer to arboist report to avoid conflict with existing trees.

Enhance landscaping including garden beds to separate / define areas following updated arborist report. Garden beds to act as safety buffer and

Retain and upgrade existing play equipment when at end of asset life.

If demand or future opportunity arises, explore the feasibility of onsite cabins

Brewery Dam



Recommendations:

- council risk assessment. Construct a new path connecting bridge to jetty.

- Replace existing jetty with a jetty with edging.
- water during a flood event.
- Install 2 new picnic tables to Council's standard.
- Protect and enhance existing vegetation.
- Council land.

Undertake drainage assessment to identify site drainage function and address the recent flooding over the weir during a storm event. Drainage assessment to be completed prior to construction of new infrastructure to avoid visitor facilities being placed in flood prone or unsafe areas.

Upgrade existing entrance signage to be consistent with Council style guide for open space reserves. Include reference to 'Take Rubbish home'.

Install appropriate safety signage and barriers as recommended in the

Construct a new path connecting Brewery Dam Road to jetty.

Revegetate area between path and water to create natural flora barriers.

Replace bridge with new bridge built or culvert crossing providing an accessible connection to the car park. This location has high volumes of

Upgrade / resurface gravel road and car park including vehicle controls to better define circulation and avoid conflict with picnic areas.

Eliminate the existing outlet through the dam wall.

Contruct a new circuit path and boardwalk around the dam. NB: drainage works to be undertaken to reduce area of water to allow path to be built on

Smythesdale Gardens

			Priority		
ltem	Recommendations:	High	Medium	Low	Indicative Cost
S1	Implement recommendations from arborist assessment and develop a Tree Replacement Strategy to retain the current landscape character as senescent trees need to be replaced. Refer to Appendix C for arborist assessment. Reference on Master Plan refers to all trees.				\$10,000 - \$20,000
S2	Restrict access and revegetate overland drainage area to create a park feature and prevent vehicles being bogged.				\$25,000 - \$50,000
S3	Undertake a drainage assessment of all roads including the entry area to identify scope of works required for upgrade. Explore options to transfer management / maintenance responsibilities for internal roads to Council and include on Council's annual unsealed road maintenance program.				\$100,000 - \$150,000
S4	Upgrade existing entrance signage and update existing internal signage. To be in accordance with Council open space reserves identification signage and consistency across the site.				\$20,000 - \$40,000
S5	Add additional historic signage within the gardens to share the rich site history.				\$10,000 - \$20,000
S6	Upgrade existing crossover at main entrance to create a safer access for vehicles with caravans i.e. prevent wheel drop-off drainage crossing.				\$10,000 - \$15,000
S7	Consider options to upgrade or replace the existing toilet and amenities facility.				\$150,000 - \$250,000
S8	Consider options to upgrade or replace the existing camp kitchen/BBQ shelter.				\$70,000 - \$80,000
S9	Investigate the level of use and ongoing demand for the existing "administration" building. If long-term use is required, upgrade/refurbish the existing building or consider building consolidation and incorporate function/s into potential amenity block upgrade.				\$10,000 - \$20,000
S10	Subject to review of Council Local Laws (i.e. fire restrictions), construct three communal campfire locations.				\$20,000 - \$40,000
S11	Upgrade the event lawn grass surface with irrigation and drainage where required.				\$20,000 - \$30,000
S12	Upgrade path network and connections to the Rail Trail and Woady Yaloak Creek.				\$40,000 - \$50,000
S13	Undertake a traffic circulation review to include internal roads and access to camping sites. Refer to arboist report to avoid conflict with existing trees.				\$50,000 - \$100,000
S14	Implement tree protection zones as recommend in the Arborist report to help maintain the health of existing tree stock. This may include extended garden beds and/or mulching and restricting camping access within designated tree protection zones.				\$150,000 - \$250,000
S15	Retain and upgrade existing play equipment when at end of asset life.				\$200,000 - \$300,000
				Total:	\$885,000 - \$1.42m

7. Implementation Framework

The following tables provide an indicative framework to guide implementation priorities over the next 10+ years. Prioritisation has considered site assessment needs, asset conditions, stakeholder input and capacity to deliver. The Master Plans provide a vehicle to assist community groups and Council to explore opportunities to source external grants and funding to support implementation.

Brewery Dam

	Item Recommendations:		Priority		
ltem			Medium	Low	Indicative Cost
B1	Undertake drainage assessment to identify site drainage function and address the recent flooding over the weir during a storm event. Drainage assessment to be completed prior to construction of new infrastructure to avoid visitor facilities being placed in flood prone or unsafe areas.				\$25,000 - \$50,000
B2	Upgrade existing entrance signage to be consistent with Council style guide for open space reserves. Include reference to 'Take Rubbish home'.				\$5000 - \$10,000
B3	Install appropriate safety signage and barriers as recommended in the council risk assessment.				\$10,000 - \$20,000
B4	Construct a new path connecting bridge to jetty.				\$25,000 - \$30,000
B5	Construct a new path connecting Brewery Dam Road to jetty.				\$5,000 - \$8,000
B6	Revegetate area between path and water to create natural flora barriers.				\$15,000 - \$25,000
B7	Replace existing jetty with a jetty with edging.				\$50,000 - \$70,000
B8	Replace bridge with new bridge built or culvert crossing providing an accessible connection to the car park. This location has high volumes of water during a flood event.				\$120,000 - \$150,000
B9	Install 2 new picnic tables to Council's standard.				\$10,000 - \$15,000
B10	Upgrade / resurface gravel road and car park including vehicle controls to better define circulation and avoid conflict with picnic areas.				\$130,000 - \$180,000
B11	Protect and enhance existing vegetation.				\$15,000 - \$25,000
B12	Eliminate the existing outlet through the dam wall.				\$2,000 - \$5,000
B13	Contruct a new circuit path and boardwalk around the dam. NB: drainage works to be undertaken to reduce area of water to allow path to be built on Council land.				\$80,000 - \$100,000
				Total:	\$492,000 - \$688,000

Appendix A

Hazard identification Risk Assesment Brewery Dam 7.02.2023

Golden Plans Shire Council - HAZARD IDENTIFICATION AND RISK ASSESSMENT

Department/unit:	Community Infrastructure	Assessment date:	7/02/2023	Incident date:	N/A
Location:	Brewery Dam – 29 Sebastopol-Smythesdale Road,	Risk Assessed as:	7/02/2023	Incident report	N/A
	Smythesdale			number:	
Description/context:	It is proposed that there may be a slight re-design	People involved in	Ryan Supple – Community Infrastructure Planner	Amount of	N/A
	of the site to include more bench seating/tables	assessment:	Kathryn Schneider – Recreation Officer	previous same or	
	to enable locals and visitors to enjoy the local		Collen Taylor – Safety and Wellbeing Advisor	similar incidents	
	flora and fauna of the site.		Mark Bluschke – Senior Business Partner Safety &	recorded:	
			Wellbeing		
	It was observed the site does not get much use				
	(observed 0 people at sight on Friday 3 rd Feb				
	2023, and encountered 2 people on risk				
	assessment date).				
	It was observed the site is predominately used for				
	yabbying.				
Additional	The site consists of a dam at the centre, with a	Person responsible	Community Infrastructure in consult with contracted	Policy/procedures	N/A
information:	creek/river that typically would fill the dam. This	for managing	consultant for the site.	or other	
	creek/river has been blocked which may have	hazard/s:		documents	
	contributed to the depth/size of the dam. This is			relevant to this	
	proposed to be rectified at an unspecified date.			risk assessment:	

Hazard * Situation, task, activity or things that have potential for harm or damage to people or things. What is the source of the risk?	Interaction/Risk *credible situation that links the hazard to the target.	Target/s *people, animals, environment or things that can be impacted.	Existing controls * What are the exact processes or things in place now to control the risk of harm? Refer to Control Hierarchy categories in Risk Matrix	Likelihood *the <u>likelihood of the</u> <u>consequence</u> <u>occurring</u> as a result of the specific interaction with the hazard. Refer to Risk Matrix descriptions for likelihood	Consequence *credible worst-case scenario (must be plausible and reasonable) if hazard interacts with target. Refer to Risk Matrix descriptions for consequence	Current Risk Rating *likelihood and consequence = risk rating Refer to Risk Matrix descriptions for risk ratings	Proposed new control measures *to reduce the current risk rating what <u>new controls</u> will you introduce to reduce the risk harm/damage? Be specific about exact control measures required.	Revised likelihood *the likelihood of the consequence occurring because of the specific interaction with the hazard now new controls are being considered?	Revised consequence *credible worst- case scenario (must be plausible and reasonable) if hazard interacts with target now new controls are being considered?	Residual risk *likelihood and consequence = risk rating	Person responsible for implementing new controls.	Comments and due date for implementing changes. • Cap Ex Budget allocation Required • Staff training to be undertaken • Consultant required • Referral to Risk Coordinator • Referral to Executive / Council
Eg: ladder climbing	Eg: falls while climbing ladder	Eg: worker	E.G. What is the type of ladder in use now? What safety factors does it have (gutter hook, non-slip feet?)	E.G. It is "Likely" that worker will die or suffer serious long- term harm/injury if they fall off ladder (major consequence).	E.G. Worst-case consequence of worker falling is "Major" – worker could die or suffer serious long term harm/injury.	E.G. The current risk rating for "Likely" and "Major" is <u>Very</u> <u>High.</u>	E.G. Now using EWP's for work above 2 metres. Training & licencing of staff for EWP use. Where use is ladder unavoidable, we have new fall restraint systems installed and gutter hooks on all ladders.	E.G. It is "Unlikely" that worker will die or suffer serious long-term harm/injury with new control measures in place.	E.G. Worst-case consequence of worker falling is now "Minor" (minor physical injury with some medical treatment required)	E.G. The risk rating for "Unlikely" and "Minor" is Low.	E.G. Team supervisor	E.G. Team supervisor to organise training for EWP by 1/9/21 Team supervisor to demonstrate and train staff to use fall restraint and gutter hooks by 1/9/21
Varying depths of water within the dam	Potential drowning in the dam	Residents and visitors to the dam	 An old sign (Appendix 1) which refers to accessing site at own risk. Natural flora barriers around deep part of the dam 	E (Rare) – there has not been a incident recorded of a person drowning within the dam. There is also no recollection from council or members of the public identifying the space as a place locals would swim	4 (Major) – although it has not happened, the consequence of a drowning would be of major consequence	E4 – Medium	 The use of some extra no- swimming signs at the entry points to site and at the small jetty The use of 'parental supervision' signs 	E (Rare)	3 (Moderate)	E3 (Low) – By providing the signage to visitors, you are educating them of the dangers posed by the dam	Community Infrastructure in consult with contracted consultant for the site.	

Small lary • Matstal access port of firm the water Passents access of dispatchering with the set of the matsol • An old sign (Community) • Filters - there has bacters the matsol with the set of dispatchering with the set of the firm with the set of		1	1	1	1	1		I I	I		· · · · · · · · · · · · · · · · · · ·
Smal Jacy • Potential transmost • And oblight • F(Pert) - Browner • And oblight • F(Pert) - Browner • In Back and the set of the set								 A sign depicting 			
Small Jetty - Protential excesses Residence and more than the company of the com											
Small Lefty - Poterinal access esdents and which effects - An od sign which effects - Effects as essential provides - Filters as essential of the specific for rouge - Poterinal access post for rouge											
Small Judy - Polyndial accoss potenting - An dd sign - Eigen-Inter the same share of the same shar											
Smal Jaffy • Potentia scores • </td <td></td>											
Smal Jaity • Potential access control • An of sign visitors to me dan basimming dia generation the jety and into the weller • <								underwater			
Small Lefty - Forlential access point of the submit of the physical bia dama - A radi sign (Approximation control more submit of the physical bia dama - A radi sign (Approximation control more submit of the physical bia dama - A radi sign (Approximation control more submit of the physical bia dama - A radi sign (Approximation control more submit of the physical bia dama - A radi sign (Approximation control more submit of the physical bia dama -								snags,			
Small Jully • Peterial access properties for several participation of the several properties for several parte properties for se								unpredictable			
Small Jully • Peterial access properties for several participation of the several properties for several parte properties for se								depths)			
Smal Jety - Potential access point for objective to the water - An old sign (Appendix 1) betwide - An old sign (Appendix 2) betwide - An old sign (Appendix											
Smal Jety - Potential access point for objective to the water - An old sign (Appendix 1) betwide - An old sign (Appendix 2) betwide - An old sign (Appendix								appendix 1 for			
Small Jetty - Potential access point for delegations to the damage of the water - An old sign (Equation to the set of the set											
Small Jefty - Potential access point for disposition for the series of class would sown - An od sign (Appendix 1) for the series of class would sown -											
Small Jetty - Potential access: Residential and output of significant of the sisis of the significant of the significant of											
Small Jefty - Potential access point for diving/swimming - Potential acates (premty oling off the water - An old sign visitors to the dam wistors to the dam the water - An old sign visitors to the dam wistors to the dam the water - An old sign visitors to the dam wistors to the dam the water - An old sign visitors to the dam wistors to the dam the water - An old sign visitors to the dam to be an an oddem to be an an oddem - An old sign visitors to the dam the water - An old sign visitors to the dam to be an an oddem - An old sign visitors to the dam to be an an oddem - An old sign visitors to the dam to be an an oddem - An old sign visitors to the dam to be an an oddem - An old sign visitors to the dam to be an an oddem - An old sign visitors to the dam to be an an oddem - An old sign visitors to the dam to be an an oddem - An old sign visitors to the dam to be an an oddem - An old sign visitors to the dam to be an an oddem - An old sign visitors to the dam to be an an oddem - An old sign visitors to the dam to be an an oddem - An old sign visitors to the dam to be an an oddem - An old sign visitors to the dam to be an an oddem - An old sign visitors to the dam to be an an oddem - An old sign visitors to the dam visitors to the dam - An old sign visitors to the dam - An old sign visitors to the dam - An old sig											
Small Jetty-Potential excess registry define water (appende) registry define water (appende) registry define the water											
Small Lety - Potential access point for diving/swimming - Residents and visitors to the dam visitors to the dam diving/swimming - - An old sign to free visitors of the ana sophied not compared to the sign of the system - An old sign (Appendix 1) the water - An old sign (Appendix 2) the compared to the sign of the system - An old sign (Appendix 1) the social do person to being an- of the global do person to being an- tecolection from the water - An old sign (Appendix 1) the social do person to being an- of the global do person to being an- tecolection from the water - An old sign (Appendix 1) the social do person to being an- of the global do person to being an- ecolection from the water - An old sign (Appendix 1) the social do person to being an- ecolection from the water - An old sign (Appendix 1) the social do person to being an- ecolection from the water - An old sign (Appendix 1) the social do person to being an- ecolection from the public detifying the public dottying the social do person to being an- ecolection from the social do person to being an- ecolection from the public dottying the public dottying th											
Small Jetty - Protencial access during swimming she during swimming she usitors to the deal being are during swimming she during swimming she the wold? - An old sign sign she during swimming she swimming she during swimming she during											
Small Jety - Potential access point for diving within the systems of being an- swimming site (appendix 1) the water - An old sign (Appendix 1) wishers to be dam swimming site (appendix 1) wishers to be dam swimming site (appendix 1) the space as a place locals would swim - An old sign (Appendix 1) wishers to be dam swimming site (appendix 3). - An old sign (Appendix 1) wishers to be dam swimming site (appendix 1) wishers to be dam swimming site (appendix 3). - An old sign (Appendix 1) wishers to be dam swimming site (appendix 3). - - An old sign (Appendix 1) wishers to be dam swimming site (appendix 3). - <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td></td> <td>water (appendix</td> <td></td> <td></td> <td></td>								water (appendix			
Smal Jetty - Potential access point for divingswimming - Potential access regress of the water - An old sign to be an another in the sace of the sace											
Small Jetty - Potential access (Parmin) - An old sign (Parmin) E(Rare) - here has no been a mole of the potential facing in the natural for as depicted in appendix 3, however, space is not dthe is potential facing (Parmin) Small Jetty - An old sign (Parmin) E(Rare) - here has no heperature of a diving symming site (Parmin) E(Rare) - here is also no mole potential facing (Parmin) E(Rare) - here has no heperature of a diving symming site (Parmin) E(Rare) - here has no heperature of a diving symming site (Parmin) E(Rare) - here has no heperature of a diving symming site (Parmin) E(Rare) - here has no heperature of a diving symming site (Parmin) E(Rare) - here has no heperature of a diving symming site (Parmin) E(Rare) - here has no heperature of a diving symming site (Parmin) E(Rare) - here has a diving symming site (Parmin) E(Rare) - here has a no heperature of a diving symming site (Parmin) E(Rare) - here has a diving symming site (Parmin) E(Rare) - here has a diving symming site (Parmin) E(Rare) - here has a diving symming site (Parmin) E(Parmin) E(Parmi											
Small Jety-Potential access (paming visitors to the dam the jety and into the jety and into the jety and into the jety and into-A nold sign (Appendix 1) which referes or swimming siteE(Rare) - there has no there is also no recollection for the potential facility (the potential facility (the potential facility (the potential facility (the potential facility) (the potential facility) (the potential facility)E(Rare) - there has a doubled of the adoubled of the solution for the site of the facilityE(Rare) - there has a doubled of consequence of a drowing winding of the jety and into the waterPotential access (Appendix 1) which referes to being a no- swimming siteE(Rare) - there has no there a incident recorded of a person the potential facility or consequence of a major conseq											
Small Jetty-Potential access (prime)Residents and wheeled dejects (prime) roling off the jetty and into the jetty and in											
Smal JettyP Potential access diving swimmingResidents and visions to the dam- An old sign (Appendix 1) which release to being a no- swimming siteE (Rare) - there has not been a incident recorded na serve to being a no- swimming siteE (Rare) - there has not been a incident recorded na serve to being a no- swimming siteE (Rare) - there has not been a incident recorded na serve to being a no- swimming siteE (Rare) - there has not been a incident recorded na serve to being a no- swimming siteE (Rare) - there has no been a incident recorded na serve to being a no- swimming siteE (Rare) - there has no been a incident recorded na serve to being a no- swimming siteE (Rare) - there has no been a incident recorded na serve to being a no- swimming siteE (Rare) - there has no been a incident recorded na serve to being a no- swimming siteE (Rare) - there has no been a incident recorded na serve to being a no- swimming siteE (Rare) - there has no been a incident recorded na serve to being a no- swimming siteE (Rare) - there has no been a incident recorded na serve to being a no- swimming siteE (Rare) - there has no been a incident recorded na serve to being a no- swimming siteE (Rare) - there has so hor necessorie to being a no- recorded na serve to being a no- swimming siteE (Rare) - there has so hor necessorie to being a no- recorded na serve to bein											
Small Jetty-Potential access point for diving/swimming pit Potential area for wheeled objects (prame joint potential area for wheeled objects (prame joint potential access (prame joint potential area for wheeled objects (prame joint potential area for wheeled objects-An old sign to bee a parson the consequence of a downE(Pare) - there has a no do sign the consequence of a downE(Pare) - there has a no do sign the consequence of a downE(Pare) - there has a no do signE(Pare) - there has a no do signE(Pare) - there has a no do sign the consequence of a down may when the consult of the jetty and into the waterPotential access a no do signE(Pare) - there has a no do signE(Pare) - there has a no do signE(A-Medum the consequence of a the consequence of a <td></td> <td></td>											
Smal Jetty-Potential access point for diving swimming -Pesidents and of diving swimming ste-An old sign (Appendix 1) swimming steE (Rare) - there has swimming ste4 (Major) - although the sate as a place local swould swimE4- Medium swimming ste-Besidents and show steSmall setty-Potential access point for diving swimming swimming ste-An old sign (Appendix 1) swimming steE (Rare) - there has swimming ste4 (Major) - although the soleE4- Medium swimming ste-E (Rare)3 (Moderate)E3 - in addition to addition to addition to addition to install degingS (Moderate)E3 - in addition to addition to addition to addition to addition to addition to sole and collection from council or members of the space as a place local swould swimE (Rare)-Provide set set3 (Moderate)E3 - in addition to addition to addition to addition to addition to onsult after at would stop the sole and collection from council or members of the public identifying the space as a place local swould swimE (Rare)-3 (Moderate)E3 - in addition to addition to addition to addition to addition to addition to addition to sole and the potential for all give as is a on consult or members of the public identifying the space as a place local swould swim											
Small Jetty-Potential access point for diving/swimming -Residents and visitors to the dam visitors to the dam-An old sign to being a no swimming siteE (Rare) - Intere has the public identifying the value4 (Major) - although the ontappendix the consequence of a the value-B (Rare)3 (Moderate)Community althoughSmall Jetty-Potential access visitors to the dam diving/swimming An old sign the valueE (Rare) - Intere has the ontappendix the consequence of a the consequence of a the value-In addition to the above, potential to install edging to the jetty. This edging could be a woodenS (Moderate)E3 - in adove, the consult with contractedCommunity infrastructure in consult with contractedSmall Jetty-Potential access visitors to the dam visitors to the dam to being a no- swimming siteE (Rare) - although the consequence of a the consequence of a the public identifying woode as a piace locals would swim-An old sign the site.E (Rare) the site.3 (Moderate)E3 - in addition to above, potential to install edging to height, This edging could be a wooden the site.E (Rare) the site.3 (Moderate)E3 - in addition to above, potential to install edging to height, This edging could be to site a the site.Community the site.Community the site.Simulty-In addition to the waterEEE (Rare)-A (Moderate)S (Moderate)E3 - in addition to the								Provision for the			
Smal Jety Potential access point for driving/swimming - An old sign to being a no drowing within the not hoppendix 1) which referes to being a no drowing within the drowing within the drowing would be of the water - An old sign to being a no drowing within the not hoppendix 1) which referes to being a no drowing within the drowing would be of the water - An old sign to being a no drowing within the not hoppendix 1) which referes to being a no drowing within the drowing would be of mereolection from could or members of the public identifying the space as a place hood swim - An old sign to being a no drowing within the not hoppendix 1) which referes to being a no drowing within the drowing would be of mereolection from could or members of the public identifying the space as a place hood swim - An old sign to being a no drowing within the hood symptom to be a sign and the consequence of a drowing would be of mereolection from could or members of the public identifying the space as a place hood show in the state of the public identifying the public identifying the prime is alson to preceive of the public identifying the public identifying the prime is alson to preceive of the public identifying the public identifying the public identifying the public identifying the prime is alson to preceive of the public identifying the prime is alson to preceive of the public identifying the prime is alson to preceive of the public identifying the public identifying the prime is alson to preceive of the public identifying the prime is alson to preceive of the public identifying the prime is alson to preceive of the public identifying the prime is installed, allow for the potential for reling to be installed as the place becomes is installed to a prime is installed to a prime is installed to a prime is installed to be installed to a prime is installed to a preceive the prime is installed to preceive the prime i											
Image: state in the state											
Small JettyPotential access point for diving/swimming 9Residents and visitors to the dam- An old sign (Appendix 1) recorded of a person dowing within the swimming siteE (Rare) - there has not been a inclent dowing within the dowing within the dowing within the swimming site- An old sign (Appendix 1) the consequence of a drowing within the drowing within the swimming siteE (Rare) - there has not been a inclent may recorded of a person drowing within the drowing within the drowing within the swimming siteE (Rare) - there has above, potential to install edging a woodenS (Moderate)S (Moderate)S (Moderate)S (Moderate)S (Moderate) addition to the addition to the addition to the sale one recorded of a person drowing would be of major consequenceE (Rare)- In addition to the above, potential to install edging out the jetty. This edging could be a woodenS (Moderate)S (Moderate)S (Moderate)S (Moderate)S (Moderate) addition to the silph barrier consultant for the sile.Community infrastructure in consultant for the sile.S (Moderate)S (M											
Small Jetty - Potential access point for diving/Swimming it which referes to being a no-swimming site (parse). E(A medium is above, potential acging to install edging to installed a stres installed as the public identifying the space as a place includes which is place beer shall be as the place beer shall b								flora as depicted			
Small JettyPotential access point for divings/wimmingResidents and vishors to the damAn old sign (Appendix 1) with referseE (Rare) - three has not been a incident recorded of a potence4 (Major) - although it has not happened, three sales on drowing would be of major consequence of the jetty and into the water9 Potential access solution of the jetty and into the waterResidents and vishor the damAn old sign (Appendix 1) with referseE (Rare) - three has not been a incident recorded of a potenceE (Ame) - although the sales on the potencial drowing would be of major consequenceE 4 - Medium above, potential to install edging to the jetty. This edging could be a woodenS (Moderate)S (Moderate)S (Bare) a diftion to a dotow, the slight barrier consult with consult with consult with consult with potencial solution the space as a place locals would swimM (Major) - although the space as a place locals would swimM (Major) - although the space as a place locals would swimM (Major) - although the space as a place locals would swimM (Major) - although the space as a place locals would swimM (Major) - although the space as a place locals would swimM (Major) - although the space as a place locals would swimM (Major) - although the space as a place locals would swimM (Major) - although the space as a place locals would swimM (M and the space as a place locals would swimM (M and the space as a place locals would swimM (M and the space as a place locals would swimM and the space as a place locals would swimM and the space as a place locals wou											
Image: series of the state ser								however, space			
Small Jetty-Potential access point for diving/swimmingResidents and visitors to the dam-A nold sign (Appendix 1) which referes swimming siteE (Rare) - there has not been a nicident drowning within the drowning within the drowning within the genesation in being and the system are of the public identifying the water4 (Major) - although the system are of the public identifying the system are as a place locals would swim4 (Major) - although the system are of the public identifying the system are as a place locals would swim5 (Rare)1 n addition to the above, potential to the jetty. This edging could be a wooden sileeper that would stop the roll of wheels3 (Moderate)E3 - in addition to addition to above, the solut with constructure in consult with contracted consult with constructure in consult with contracted consult with consult with contracted consult w											
Image: constraint of the potential access point for diving/swimming Residents and visitors to the dam diving/swimming - An old sign a not serve to being a no swimming site to being a no swimming site to being a no swimming site the qubic identifying the pace as a place locals would swim 4 (Major) - although the consequence of a drowning would be of major consequence - In addition to the above, the onsequence of a drowning would be of major consequence S (Rare) - here has adving would be of major consequence E (Are) 3 (Moderate) E (Are) 3 (Moderate) E (Are) A division to above, the sight barrier consultant for the objects rolling off the pietry and into the public identifying the space as a place locals would swim Concernence of a drowning would be of major consequence Figure a major consequence											
Small Jetty - Potential access point for diving/swimming - An old sign obsen a incident not been a incident not been a incident swimming site E (Rare) - there has not happened, the consequence of a person drowning within the jetty and into the jetty and into the water - An old sign obsen a incident not been a incident neoteen a inc											
point for diving/swimming - Potential area for wheeled objects (prams) rolling off the jetty and into the watervisitors to the dam(Appendix 1) which referes to being a no- swimming sitenot been a incident recorded of a person drowing within the drowing within the drowing within the drowing within the drowing within the percenter of a difference the jetty and into the watervisitors to the dam(Appendix 1) which referes to being a no- swimming sitenot been a incident recorded of a person drowing within the drowing would be of major consequenceabove, potential to install edging to the jetty. Thisaddition to above, the slight barrier consult with consult with would stop the roll of wheels (appendix 3), i frabove is installed, allow for the potential for railing to be installed, allow for the potential for railing to be installed as the place becomesaddition to above, potential to install edging slopesaddition to above, potential to install edging would stop the roll of wheels installed, allow for the potential for railing to be installed as the place becomesaddition to addition to above, the 	Small latty	Detential access	Decidente and	An old sign	E (Para) there has	1 (Major) although	E4 Modium		2 (Mederate)	E2 in	Community
diving/swimming which referes recorded of a person the consequence of a to install edging to the jetty. This above, the slight barrier consult with (prams) rolling off the jetty and into the explete dotients major consequence above, the slight barrier consult with (prams) rolling off the water the water above, the slight barrier consultant for (prams) rolling off the water above, the slight barrier consultant for (prams) rolling off the space as a place locals would swim locals would swim locals would swim slight barrier consultant for (prams) rolling off the space as a place locals would swim local						it bac not bonnoned					
wheeled objects (prams) rolling off the jetty and into the water swimming site (prams) rolling off the jetty and into the water dam. There is also no recollection from council or members of the public identifying the space as a place locals would swim major consequence seleper that would stop the roll of wheels (appendix 3). edging could be a wooden seleper that would stop the roll of wheels (appendix 3). consultant for the site. the site.				(Appendix I)		the consequence of a		to install adding			
wheeled objects (prams) rolling off the jetty and into the water swimming site (prams) rolling off the jetty and into the water dam. There is also no recollection from council or members of the public identifying the space as a place locals would swim major consequence seleper that would stop the roll of wheels (appendix 3). edging could be a wooden seleper that would stop the roll of wheels (appendix 3). consultant for the site. the site.		Detential area for		to being a po	drowning within the	drowning would be of		to the jetty This		above, the	consult with
(prams) rolling off the jetty and into the water recollection from council or members of the public identifying the space as a place locals would swim a wooden sleeper that would stop the roll of wheels installed, allow for the potential for railing to be place becomes chance of wheeled objects rolling off the jetty the site.								to the jetty. This			
the jetty and into the water council or members of the public identifying the space as a place locals would swim sleeper that would stop the roll of wheels (appendix 3). wheeled objects rolling off the jetty - If above is installed, allow for the potential for railing to be installed as the place becomes wheeled objects				swimming site		major consequence					
the water the water the water the public identifying the space as a place locals would swim locals would swim locals would swim with space as a place locals would swim locals		(prams) rolling off									the site.
the space as a place locals would swim											
Iocals would swim (appendix 3). jetty - If above is installed, allow for the potential for railing to be installed as the place becomes jetty		the water								objects	
- If above is installed, allow for the potential for railing to be installed as the place becomes											
installed, allow for the potential for railing to be installed as the place becomes					locals would swim			(appendix 3).		jetty	
for the potential for railing to be installed as the place becomes											
for railing to be installed as the place becomes											
installed as the place becomes											
place becomes											
more nonular											
								more popular.			

Appendix 1



Current signage at Brewery Dam



Signage used at Lethbridge Lake, larger area than Brewery Dam. Proposed to use this type of signage.



Signage used at watering hole in Grampians. Provided as an example.

Appendix 2

Smythesdale Gardens & Brewery Dam Reserve aster Plan





Potential design if space becomes more popular and after an addition risk assessment



Appendix 3

Jetty at Brewery Dam



Proposed type of edging (not as thick) to avoid roll off

Risk Control Action and Implementation Plan

Smythesdale Gardens & Brewery Dam Reserve Master Plan

1. List each of the identified control measures

3. Determine a date by which to evaluate the effectiveness of the risk controls

2. List the due date, the date the control was implemented and by whom

4. Evaluate the effectiveness of the risk controls and determine the residual risk rating

ACTION AND IMPLEMENTATION PLAN								
Risk Control / Action (List the identified Risk Controls)	Due Date (By what date will this be done?)	(What date was the control implemented?)	Implemented By (Who implemented the control?)	Evaluation Date (When will the control be evaluated?)	Actual Residual Risk Rating (What is the risk level after the evaluation?)			
Installation of signs at entry points to dam and jetty. - Signs to be of AS 1319			Community Infrastructure in consult with contracted consultant for the site.					
Tidy-up of natural flora barriers			Community Infrastructure in consult with contracted consultant for the site.					
Potential instal of sleeper around jetty edge			Community Infrastructure in consult with contracted consultant for the site.					

RISK CONTROL EVALUATION:

Provide comment on the effectiveness of the Risk Control including how the risk control was evaluated?

* If ongoing evaluation, review or checks are required, add to relevant Operational Checklists and/or Training and Preventative Maintenance Schedules

Smythesdale Gardens & Brewery Dam Reserve Nan-Plan

Table 1: Likelihood Ratings							
Likelihood	Category	Description					
Almost Certain	A	Event expected to occur most times during formal operations or in most circumstances					
Likely	В	Will probably occur at some stage based on evidence of previous incidents. Will probably occur in most circumstances					
Possible	C	Not generally expected to occur but may under specific circumstances. Should occur at some time					
Unlikely	D	Conceivable but not likely to occur under normal operations; no evidence of previous incidents					
Rare	E	Only ever occurs under exceptional circumstances					

Table 3: Levels of Risk Matrix

Likelihood	Consequence					
	1 - Negligible	2 - Minor	3 - Moderate	4 - Major	5 - Catastrophic	
A Almost Certain	Medium	High	High	Very High	Very High	
B Likely	Medium	Medium	High	Very High	Very High	
C Possible	Low	Medium	Medium	High	Very High	
D Unlikely	Low	Low	Medium	High	High	
E Rare	Low	Low	Low	Medium	High	
Very High - Immediate action required. Executive attention required to ensure appropriate and required controls are in place.			High - Prompt action required. Manager, Coordinator and/or Team Leader close supervision required to implement additional controls and report to Executive on actions.			
Medium - Current identified controls should apply. Managers responsible for ensuring controls are and continue to be effective.			Low - Monitor for changed conditions. Controls are appropriate and to be monitored for ongoing suitability			

Consequence	Category	Description
Catastrophic	5	Extensive fi threatens v disaster ma attention, l
Major	4	Major finar environmen injury, seric functions, r litigation
Moderate	3	Significant environme lost medica or breach in public critic
Minor	2	Minor finar with some which can b heightened
Negligible	1	Negligible f isolated cor minimal fai

Control Hierarchy

The control hierarch is a list of control measures, in priority order, th exposure to hazards.

Below is the control hierarchy with general examples of each control

Elimination: Avoid the risk by removing the hazard completely.

Substitution: Use less hazardous procedures, substances, equipment

Isolation: Separate the hazard by the use of barriers, enclosures or di

Engineering Controls: Mechanical or physical changes to equipment,

Administrative Controls: Change procedures to reduce exposure to the hazard

Personal Protective Equipment (PPE): Gloves, goggles, enclosed shoes etc.

on
financial loss (>\$1M), multiple fatalities, viability of business, extensive litigation, nanagement required, national media loss of function across organisation
ancial loss (\$500k - \$1M), Major physical or ental impact, fatality or serious long term rious public or media outcry, loss of critical IT , major breach of obligations/law leading to
t financial loss (\$50K-\$500K), significant ental impact, significant injury involving time cal treatment and hospitalisation, complaint involving a statutory body and investigation, cicism with or without media attention
ancial loss (\$10k - \$50k), minor physical injury e medical treatment required, minor event b be contained and managed internally, ed community concern or criticism
financial loss (\$<10k), first aid only required, omplaint with minimal adverse attention, ailure of internal controls
nat can be used to eliminate or minimise
l measure:
t or process.
listance.
, materials or process.

Appendix B

Symthesdale Gardens Arborist report 12.02.2014




Smythesdale Gardens & Brewery Dam Reserve Master Plan







Golden Plains Shire, Smythesdale Botanic Gardens - Total Tree Inventory by Risk (175 Trees)



Smythesdale Gardens & Brewery Dam Reserve Master Plan

12 Trees (6.86%)

3 Trees (1.71%)

23 Trees (13.14%)



Appendix C

Symthesdale Gardens Arborist report 11.05.2023



Tree/s Location: Smythesdale Gardens, VIC 3351 Completed for: Golden Plains Shire Inspection date: 18, 19 & 20 April 2023 Date of report: 11 May 2023

Prepared by: Jimmy Ross, Consulting Arborist Diploma of Arboriculture, Fairfield Polytechnic (Level 5) Phone: 0415 944 987 Email: info@treecareconsulting.com.au ACN: 637 683 339 ABN: 14 637 683 33



Arboricultural Hazard Assessment. The Grace McKellar Centre, 45-95 Ballarat Road, North Geelong, VIC 3215

5. TREE AUDIT

For the purposes of the audit, trees have been given a colour code to indicate priority. The following timeframes for work to be completed apply to these priorities:

Low	12 months
Moderate	3 months
High	1 month

The colour code within the audit corresponds with the tree numbering on the provided site map.

5. TREE LOCATIONS



Smythesdale Gardens & Brewery Dam Reserve Master Plan





2 Pope Street, Bannockburn, VIC 3331 19 Heales Street, Smythesdale, VIC 3351

PO Box 111, Bannockburn, VIC 3331

@ enquiries@gplains.vic.gov.au

goldenplains.vic.gov.au

CUSTOMER HUB HOURS Golden Plains Civic Centre, Bannockburn

8.30am to 5pm, Monday to Friday

The Well, Smythesdale

8.30am to 5pm, Monday to Friday

@GPSCouncilNews

- Iovegoldenplains
- (f) GoldenPlainsShire
- **f** GoldenPlainsMayor